



### Abandoned Mineral Mine Lands

#### A. SITE IDENTIFICATION

Date of Inspection (MM/DD/YYYY): 7/14/2011

Date Record Updated (MM/DD/YYYY): 7/26/2021

Mineral Mining Number: DMM12117

Inventory Author: BISHOP

MRDS Number: W000423

Author Affiliation: VA DMME - DMM

MRV Number: MRV183C\_108

Mine Name: \_\_\_\_\_

Acres: 2.000

Minerals: GOLD

HUC: RA43

County: Orange

Quadrangle: Chancellorsville

BOND FOREITURE  PERMITTED

Latitude: 38.343012

Longitude: -77.723890

#### B. Project Information (For Non-Permitted Sites only)

Project Number: \_\_\_\_\_

OLAC Ranking: \_\_\_\_\_

Olac Notes:

Brownfield Potential     Carbon Storage Potential     Economic Development Potential

#### C: SITE HISTORY

Mine Owner: \_\_\_\_\_

DMM Permit: \_\_\_\_\_

Date Last Mined: \_\_\_\_\_

Date First Mined: \_\_\_\_\_

MineType: Prospect

Shafts on Site: \_\_\_\_\_

Depth Below(feet): 300.00

Working Length: \_\_\_\_\_







---

### Abandoned Mineral Mine Lands

Potable Water Supplies at risk, if yes check box

At Risk Potable Water Supply Notes:

---

No of Horizontal Caved  
Entrances: \_\_\_\_\_

No of Horizontal Open  
Entrances: \_\_\_\_\_

Horizontal Entrance Notes:

---

Existence of High Walls at the Site, if yes check box

High Walls Notes:

---

Existence of Impoundments at Site, if yes check box

Impoundment Notes:

---

Existence of Unstable Slopes at Site, if yes check box

Unstable Slop Notes:

---

Existence of Subsidence Areas, if yes check box

Subsidence Area Notes:

---

Number of Mine Dumps at Site: \_\_\_\_\_

Mine Dump Notes:

---

Structure / Equipment Evaluation: None

Structure / Equipment Notes:

---

## Abandoned Mineral Mine Lands

---

### G. REFERENCES

References Results:

---

### H. MONITORING

Monitoring Results:

---

### I. CORRESPONDENCE

Date	Type	Comments
5/17/2012		